

Health, Safety, Environmental, Product Stewardship and Sustainability 115 Tabor Road Morris Plains, NJ 07950 www.honeywell.com

April 26, 2018

Mr. Edward Hammerberg
Technical Specialist/RCE Supervisor
Waste Division and Utilization Program
Maryland Department of the Environment
1800 Washington Boulevard, Suite 645
Baltimore, MD 21230

Re: Transmittal of Quarterly Site Progress Report, First Quarter 2018, 2000 Race Street Site, Baltimore, Maryland

Dear Mr. Hammerberg:

Please find attached the First Quarter 2018 Site Progress Report for the 2000 Race Street Site, Baltimore, Maryland. This document is provided on behalf of Honeywell and the Mayor and City Council of Baltimore pursuant to the requirements of Section III.A of the 2000 Race Street Site Consent Order effective May 23, 2007.

If you have any questions or require additional information, please do not hesitate to contact me at 973-455-3302, or by e-mail at Maria. Kaouris@Honeywell.com.

Sincerely,

Maria Kaouris

Remediation Manager

Attachment

cc: Mr. Ed Dexter-MDE

Mr. Al Simpkins—MDE

Canui

Mr. Michael Daneker—Arnold & Porter Ms. Dawn Lettman—City of Baltimore Mr. Ravic Miller—City of Baltimore

Mr. Christopher French—Honeywell

First Quarter 2018 Race Street Quarterly Site Progress Report, 2000 Race Street, Baltimore, Maryland

Prepared for

Honeywell and Mayor and City Council of Baltimore, Maryland

April 2018



Contents

Α

Site Inspection Reports

Section	n	Page
1.	Introduction	1
2.	Quarter in Review	1
3.	Upcoming Work and Submittals during the Second Quarter of 2018	2
4.	Schedule	2
Appen	dixes	

First Quarter 2018 Race Street Quarterly Site Progress Report, 2000 Race Street, Baltimore, Maryland

1. Introduction

Honeywell International Inc. (Honeywell) and the Mayor and City Council of Baltimore (City) are submitting this Quarterly Site Progress Report for the 2000 Race Street Site (Site) pursuant to the May 23, 2007, Administrative Consent Order (Consent Order) between the Maryland Department of the Environment (MDE), Honeywell, and the City. Quarterly Site Progress Reports will be submitted to MDE for the duration of the Consent Order. As specified within Section III.F of the Consent Order, the reports are required to include the following information:

- Work completed and documents submitted to MDE in the preceding quarter;
- A schedule and submittals for the upcoming quarter; and
- Any delays, modifications, or changes anticipated in the upcoming quarter.

This report covers Site-related activities conducted under the Consent Order during the first quarter of 2018, from January 1, 2018, through March 31, 2018.

The Site is located at 2000 Race Street, in Baltimore, Maryland (ZIP Code 21230). It occupies approximately 10.3 acres and is bounded on the north by the Baltimore Gas and Electric Spring Gardens facility, on the south by Swann Park, on the east by Race Street, and on the west by the Middle Branch of the Patapsco River. In addition, two elevated spans of Interstate 95 (I-95) oriented from east to west, overlie the Site on the northern half of the property. A chain-link security fence is present at the perimeter of the Site. The Site has no onsite building structures and is currently vacant.

Controlled hazardous substances are contained on the Site and covered with an engineered cap consisting of the following materials from top to bottom: asphalt, gravel base, and compacted clay. Cap maintenance is ongoing. Additional information regarding the Site is provided in several documents, including the May 23, 2007, Consent Order; the *Site Characterization Work Plan*, dated September 2007; the *Site Characterization Report*, dated September 2009; the *Near Shore Investigation Report*, dated December 2009; and the *Interim Remedial Measures Assessment Investigation and Pilot Test Report*, dated July 2012.

2. Quarter in Review

Site-related activities performed during the first quarter of 2018 include the following:

- January 1–30: Permeable Reactive Barrier (PRB) installation in progress;
- January 17: Project Coordinator call with MDE;
- January 25: Monthly Site status inspection (Appendix A);
- January 29: Fourth Quarter 2017 Site Progress Report submitted to MDE:
- February 1–28: PRB installation in progress;
- February 22: Monthly Site status inspection (Appendix A);
- February 26: Arsenic Shed Site Characterization Report submitted to MDE;

- February 28: Project Coordinator call with MDE;
- March 1–31: PRB installation (site restoration) in progress;
- March 14: Surface cover maintenance inspection;
- March 29: Project Coordinator call with MDE; and
- March 29: Monthly site status inspection (Appendix A).

3. Upcoming Work and Submittals during the Second Quarter of 2018

The following activities and submittals are anticipated to occur in the upcoming quarter:

- Conduct monthly Site status inspections and participate in monthly Site status calls with MDE (April, May, and June);
- Submit the First Quarter 2018 Site Progress report;
- Perform quarterly Shape Accel Array (SAA)/inclinometer readings; and
- Complete site restoration and cap maintenance following PRB installation.

4. Schedule


A schedule of Consent Order activities anticipated during the second quarter of 2018 is provided below.

Milestone	Anticipated Date
April 2018	
Perform monthly site status inspection	4-26-18
Submit Q1 2018 Site Progress report	4-30-18
Site restoration following PRB installation	4-2018
May 2018	
Prepare PRB Operation, Maintenance, and Monitoring Plan	TBD
Perform monthly site status inspection	TBD
June 2018	
Perform monthly Site Status inspection	TBD
Perform quarterly SAA/inclinometer readings	TBD

Appendix A Site Inspection Reports


Inspector:	Bill Morris	Date of Inspection:		25-Jan-18	
Title:	Environmental Engineer	Date of Last Inspection:		25-Dec-17	
Organization:	CH2M HILL	Weather:	Sunny, cool		
Site Inspection	Results			1	
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations	
1. General	0200114410110	, totalio i diteri	Date Completed	Commenter, talanterial Cases value in	
Inspect site for presence of surface debris. Identify type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Sediment and debris accumulation. Trash accumulation	City representatives onsite during inspection.	NA	Sediment, debris, and vegetation to be removed during Q2 2018 as part of scheduled site maintenance and cap repairs	
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA	
2. Interstate 95 Footings and Joints	I	I	T		
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA	
	None	None	NA	NA	
3. Engineered Cap					
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	7: Alligator cracking in asphalt near fence line.	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.	
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	10: Hole in asphalt outside of fence 2: Damage to asphalt covering slope. 8: Erosion in grass covered slope.	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.	
Inspect cap for cracks less than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Crack with vegetation between inlet grate and asphalt. Crack in asphalt with vegetation growth 5,: Crack between pier footing and asphalt.	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.	
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA .	
Inspect cap for any signs of ponding of water	9: Ponding water on asphalt	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.	
Inspect shorefront embankment for evidence of erosion or releases	None	None	NA	NA	

Site Inspection	Results			
Task	Observations	Actions Taken	Date Comp	oleted Comments/Additional Observations
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA
4. Fence			<u>'</u>	-
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA
	None	None	NA	NA
Inspect gates, chains, and locks for damage	None	None	NA	NA
Inspect fence to determine if any vegetation is damaging or otherwise compromising fence	None	None	NA	NA NA
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA
5. Aboveground Storm water Conveyance System	n			
Inspect aboveground storm water conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	None	None	NA	NA
6. Vandalism			•	-
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA
Identify any other observations related to vandalism on the site	None	None	NA	NA
7. Signage				
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)		None	NA	NA
8. Miscellaneous Items	<u> </u>	I		1
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Sylvia Osis and Al Simkins of MDE and Abscope was onsite working on the PR		nore DOT were or	nsite for the monthly inspection. A construction crew from
Other Comments/Observations?				



Inspector:	Bill Morris	Date of Inspection:	22-Feb-18	
Title:	Environmental Engineer	Date of Last Inspection:	25-Jan-18	
Organization:	CH2M HILL	Weather:	Cool, cloudy	
Site Inspection	Results			
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
1. General				
Site Inspection Checklist).	Sediment and debris accumulation. Trash accumulation Metal debris	City representatives onsite during inspection.	NA	Sediment, debris, and vegetation to be removed during Q2 2018 as part of scheduled site maintenance and cap repairs
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
2. Interstate 95 Footings and Joints			1	
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
	None	None	NA	NA
3. Engineered Cap			1	
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	8: Alligator cracking in asphalt near fence line.	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.
	11: Hole in asphalt outside of fence 2: Damage to asphalt covering slope. 9: Erosion in grass covered slope.	None	NA	Surface cover repairs to be addressed in 2018 as part of scheduled site maintenance and cap repairs.
	Crack with vegetation between inlet grate and asphalt. Crack in asphalt with vegetation growth 5: Crack between pier footing and asphalt.	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA
Inspect cap for any signs of ponding of water	10: Ponding water on asphalt	None	NA	Surface cover repairs to be addressed during 2018 as part of scheduled site maintenance and cap repairs.
Inspect shorefront embankment for evidence of erosion or releases	None	None	NA	NA

Site Inspection	Results			
Task	Observations	Actions Taken	Date Comp	oleted Comments/Additional Observations
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA
4. Fence		1	u	-
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA
Inspect gates, chains, and locks for damage	None	None	NA	NA
Inspect fence to determine if any vegetation is damaging or otherwise compromising fence	None	None	NA	NA NA
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA
5. Aboveground Storm water Conveyance System	1		<u> </u>	
Inspect aboveground storm water conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	None	None	NA	NA
6. Vandalism			I	
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA
Identify any other observations related to vandalism on the site	None	None	NA	NA
7. Signage			•	
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)		None	NA	NA
8. Miscellaneous Items	<u> </u>			1
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Al Simkins of MDE was onsite for the minspection. A construction crew from Al			ith the Baltimore City DOT were onsite for the monthly
Other Comments/Observations?	None			



Inspector:	Bill Morris	Date of Inspection:		29-Mar-18	
Title:	Environmental Engineer	Date of Last Inspection:		22-Feb-18	
Organization:	CH2M HILL	Weather:		Sunny, warm	
Site Inspection					
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations	
1. General	0200.1440.10	, totalis i alteri	Date Completed	Commonto, tautional Coort autono	
Inspect site for presence of surface debris. Identify type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Sediment and debris accumulation. Trash accumulation	City notified	NA	Sediment, debris, and vegetation to be removed during Q2 2018 as part of scheduled site maintenance and cap repairs	
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA	
2. Interstate 95 Footings and Joints					
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA	
	None	None	NA	NA	
3. Engineered Cap					
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	5: Alligator cracking in asphalt	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.	
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	15: Hole in asphalt outside of fence 8: Damage to asphalt covering slope. 14: Erosion in grass covered slope.	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.	
Inspect cap for cracks less than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	7: Crack with vegetation between inlet grate and asphalt. 13: Crack in asphalt with vegetation growth 10: Crack between pier footing and asphalt.	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.	
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	4: Crack in asphalt with vegetation growth	None	NA	NA	
Inspect cap for any signs of ponding of water	6: Ponding water on asphalt	None	NA	Surface cover repairs to be addressed in 2018 as part of scheduled site maintenance and cap repairs.	
Inspect shorefront embankment for evidence of erosion or releases	None	None	NA	NA	

Site Inspection	Results			
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
Identify any other observations related to the condition of the cap and potential for cap damage	3: Damage to asphalt	None	NA	Surface cover repairs to be addressed during Q2 2018 as part of scheduled site maintenance and cap repairs.
4. Fence				
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA
Inspect gates, chains, and locks for damage	None	None	NA	lna
Inspect fence to determine if any vegetation is damaging or otherwise compromising fence	None	None	NA	NA
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	12: Fence corroded	None	NA	NA
5. Aboveground Storm water Conveyance System	n	-	l .	
Inspect aboveground storm water conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	None	None	NA	NA
6. Vandalism		<u> </u>	I	
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA
Identify any other observations related to vandalism on the site	2: Spray paint on pile cap 11N	None	NA	NA
7. Signage		-		
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)		None	NA	NA
8. Miscellaneous Items	<u> </u>			<u>I</u>
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Al Simkins of MDE was onsite for the	monthly inspection. A Maryland Trans	portation Authority crew	was onsite to add a new lock to front gate.
Other Comments/Observations?	1: Damage to well and bollards. Well will be repaired as part of site maintenance.			

