

**Health, Safety, Environmental, Product Stewardship and Sustainability** 115 Tabor Road Morris Plains, NJ 07950 www.honeywell.com

April 25, 2019

Mr. Edward Hammerberg
Technical Specialist/RCE Supervisor
Waste Division and Utilization Program
Maryland Department of the Environment
1800 Washington Boulevard, Suite 645
Baltimore, MD 21230

Re: Transmittal of Quarterly Site Progress Report, First Quarter 2019, 2000 Race Street Site, Baltimore, Maryland

Dear Mr. Hammerberg:

Please find attached the First Quarter 2019 Site Progress Report for the 2000 Race Street Site, Baltimore, Maryland. This document is provided on behalf of Honeywell and the Mayor and City Council of Baltimore pursuant to the requirements of Section III.A of the 2000 Race Street Site Consent Order effective May 23, 2007.

If you have any questions or require additional information, please do not hesitate to contact me at 973-455-3302, or by e-mail at Maria. Kaouris@Honeywell.com.

Sincerely,

Maria Kaouris

Remediation Manager

Attachment

cc: Mr. Ed Dexter- MDE

Mr. Al Simpkins -MDE

Mr. Michael Daneker - Arnold & Porter

Ms. Dawn Lettman - City of Baltimore

Mr. Ravic Miller - City of Baltimore

Mr. Christopher French - Honeywell

# FIRST QUARTER 2019 RACE STREET QUARTERLY SITE PROGRESS REPORT

# $2000\,\mathrm{RACE}\,\mathrm{STREET}$ BALTIMORE, MARYLAND

Prepared for



115 Tabor Road Morris Plains, New Jersey 07950

Prepared by



Jacobs Engineering 2411 Dulles Corner Park Suite #500 Herndon, VA 20171

April 2019



# Contents

1.	Introduction1
2.	Quarter in Review1
3.	Upcoming Work and Submittals during the Second Quarter of 20191
4.	Schedule2

# **Appendixes**

A Site Inspection Reports

i



### 1. Introduction

Honeywell International Inc. (Honeywell) and the Mayor and City Council of Baltimore City (City) are submitting this Quarterly Site Progress Report for the 2000 Race Street Site (Site) pursuant to the May 23, 2007, Administrative Consent Order (Consent Order) between the Maryland Department of the Environment (MDE), Honeywell, and the City. Quarterly Site Progress Reports will be submitted to MDE for the duration of the Consent Order. As specified within Section III.F of the Consent Order, the reports are required to include the following information:

- Work completed, and documents submitted to MDE in the preceding quarter;
- A schedule and submittals for the upcoming quarter; and
- Any delays, modifications, or changes anticipated in the upcoming quarter.

This report covers Site-related activities conducted under the Consent Order during the first quarter of 2019, from January 1, 2019, through March 31, 2019.

The Site is located at 2000 Race Street, in Baltimore, Maryland (ZIP Code 21230). It occupies approximately 10.3 acres and is bounded on the north by the Baltimore Gas and Electric Spring Gardens facility, on the south by Swann Park, on the east by Race Street, and on the west by the Middle Branch of the Patapsco River. In addition, two elevated spans of Interstate 95 (I-95) oriented from east to west, overlie the Site on the northern half of the property. A chain-link security fence is present at the perimeter of the Site. The Site has no onsite building structures and is currently vacant.

Controlled hazardous substances are contained on the Site and covered with an engineered cap consisting of the following materials from top to bottom: asphalt, gravel base, and compacted clay. Cap maintenance is ongoing. Additional information regarding the Site is provided in several documents, including the May 23, 2007, Consent Order; the Site Characterization Work Plan, dated September 2007; the Site Characterization Report, dated September 2009; the Near Shore Investigation Report, dated December 2009; the Interim Remedial Measures Assessment Investigation and Pilot Test Report, dated July 2012; and the Supplemental Site Characterization Report (former arsenic shed area), date February 2018.

# 2. Quarter in Review

Site-related activities performed during the first guarter of 2019 include the following:

- January 9: Project Coordinator call with MDE;
- January 24: Monthly Site status inspection (Appendix A);
- January 30: Fourth Quarter 2018 Site Progress Report submitted to MDE;
- February 12: Project Coordinator call with MDE;
- February 28: Monthly Site status inspection (Appendix A);
- March 21: Monthly Site status inspection (Appendix A);
- March 22: Project Coordinator call with MDE; and
- March 25: Submit response to comments to MDE.

# 3. Upcoming Work and Submittals during the Second Quarter of 2019

The following activities and submittals are anticipated to occur in the upcoming quarter:

# **Honeywell**

- Conduct monthly Site status inspections and participate in monthly Site status calls with MDE (April, May, and June);
- Submit the First Quarter 2019 Site Progress report;
- Perform quarterly Semi-annual Shape Accel Array (SAA)/inclinometer readings; and
- Submit final Corrective Measures Alternatives Analysis (CMAA) and the Post-Closure CHS Permit Application to MDE; and
- Submit Second Half 2018 Bridge Monitoring Report to MDE.

Honeywell and the City previously submitted to MDE the following reports:

- Interim Remedial Measures Assessment (IRMA) Determination Report;
- Corrective Measures Alternatives Analysis (CMAA); and
- Post-Closure Controlled Hazardous Substance (CHS) Permit Application.

MDE has been reviewing and provided comments on the CMAA and CHS documents, which Honeywell and the City have addressed and integrated into updated documents. MDE has indicated that it expects to complete its review shortly, which will then enable the documents to be finalized, a Public Notice to be issued for the Post-Closure Permit and CMAA, and public hearing to be scheduled on the Tentative Determination.

# 4. Schedule


A schedule of Consent Order activities anticipated during the second quarter of 2019 is provided below.

Milestone	Anticipated Date
April 2019	
Perform monthly site status inspection	4-18-19
Submit Q1 2019 Site Progress report	4-30-19
M ay 2019	
Perform monthly site status inspection	TBD
Perform quarterly SAA/inclinometer readings	TBD
June 2019	
Perform monthly Site Status inspection	TBD

# Appendix A Site Inspection Reports


Inspector:	Bill Morris	Date of Inspection:	24-Jan-19	
Title:	Environmental Engineer	Date of Last Inspection:	20-Dec-18	
Organization:	CH2M HILL	Weather:	Cool, rain	
01.1	D			
Site Inspection		A stiens Teles	D-4- Ol-4- d	C
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
General Inspect site for presence of surface debris. Identify type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	8: Sediment and debris accumulation with vegetation growth			Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
2. Interstate 95 Footings and Joints				
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
	None	None	NA	NA
3. Engineered Cap				
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
Inspect cap for cracks less than 0.5 inches wide.  Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Crack in asphalt with vegetation growth     Crack between pier footing and asphalt     with vegetation growth	None		Surface cover repairs to be addressed in 2019 as part of scheduled site maintenance and cap repairs.
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Wide crack in asphalt with vegetation growth     Crack between pier footing and asphalt with vegetation growth	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.
Inspect cap for any signs of ponding of water	None	None	NA	NA
Inspect shorefront embankment for evidence of erosion or releases	None	None	NA	NA
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA
4. Fence	1	1		

Site Inspection	Results					
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations		
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA		
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA		
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA		
Inspect gates, chains, and locks for damage	None	None	NA	NA .		
Inspect fence to determine if any vegetation is damaging or otherwise compromising fence	3: Vegetation growth along fence	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.		
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA		
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA		
5. Aboveground Stormwater Conveyance System	n		•			
Inspect aboveground stormwater conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	Disconnected downspout     Hole in downspout piping     Leak conveyance piping under elevated highway	MDTA notified of need for repairs to downspouts and piping	1/25/2019			
6. Vandalism		•				
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA		
Identify any other observations related to vandalism on the site	None	None	NA	NA		
7. Signage		•				
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA		
8. Miscellaneous Items						
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Al Simkins with MDE was onsite for the monthly inspection.					
Other Comments/Observations?	None					



Inspector:	Bill Morris	Date of Inspection:	28-Feb-19	
Title:	Environmental Engineer	Date of Last Inspection:	24-Jan-19	
Organization:	CH2M HILL	Weather:	Sunny, cool	
Site Inspection	Results			
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
1. General	0200174410110	Actions Taken	Bate Completed	Commence, additional Operivations
Inspect site for presence of surface debris. Identify type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	7: Sediment and debris accumulation with vegetation growth	None		Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
2. Interstate 95 Footings and Joints				
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
	None	None	NA	NA
3. Engineered Cap				
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA .
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
Inspect cap for cracks less than 0.5 inches wide.  Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Crack in asphalt with vegetation growth     Crack between pier footing and asphalt     with vegetation growth	None		Surface cover repairs to be addressed in 2019 as part of scheduled site maintenance and cap repairs.
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Wide crack in asphalt with vegetation growth     Crack between pier footing and asphalt with vegetation growth	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.
Inspect cap for any signs of ponding of water	None	None	NA	NA
Inspect shorefront embankment for evidence of erosion or releases	None	None		NA
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA
4. Fence		I.		

Site Inspection	Results				
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations	
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA	
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA	
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA	
Inspect gates, chains, and locks for damage	None	None	NA	INA .	
Inspect gates, shall be any vegetation is damaging or otherwise compromising fence	4: Vegetation growth along fence	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.	
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA	
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA	
5. Aboveground Stormwater Conveyance System					
Inspect aboveground stormwater conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	Disconnected downspout     Hole in downspout piping	MDTA notified of need for repairs to downspouts and piping	1/25/2019	NA	
6. Vandalism		•			
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA	
Identify any other observations related to vandalism on the site	None	None	NA	NA	
7. Signage			I.		
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA	
8. Miscellaneous Items					
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Al Simkins with MDE was onsite for the monthly inspection.				
Other Comments/Observations?	None				



	_						
Inspector:	Bill Morris	Date of Inspection:	21-Mar-19				
Title:	Environmental Engineer	Date of Last Inspection:	28-Feb-19				
Organization:	CH2M HILL	Weather:		Cool, rain			
Site Inspection Results							
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations			
1. General	Observations	Actions Taken	Date Completed	Comments/Additional Observations			
Inspect site for presence of surface debris. Identify type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	7: Sediment and debris accumulation with vegetation growth	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.			
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA			
2. Interstate 95 Footings and Joints							
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA			
	None	None	NA	NA			
3. Engineered Cap							
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA			
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA			
	Crack in asphalt with vegetation growth     Crack between pier footing and asphalt     with vegetation growth	None	NA	Surface cover repairs to be addressed in 2019 as part of scheduled site maintenance and cap repairs.			
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	Wide crack in asphalt with vegetation growth     Crack between pier footing and asphalt with vegetation growth	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.			
Inspect cap for any signs of ponding of water	None	None	NA	NA			
Inspect shorefront embankment for evidence of erosion or releases	None	None		NA			
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA			
4. Fence		ı	ı				

Site Inspection	Results				
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations	
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA	
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA	
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA	
Inspect gates, chains, and locks for damage	None	None	NA	INA .	
Inspect gates, shall be any vegetation is damaging or otherwise compromising fence	4: Vegetation growth along fence	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of scheduled site maintenance.	
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA	
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA	
5. Aboveground Stormwater Conveyance System					
Inspect aboveground stormwater conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	Disconnected downspout     Hole in downspout piping	MDTA notified of need for repairs to downspouts and piping	1/25/2019	NA	
6. Vandalism		•			
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA	
Identify any other observations related to vandalism on the site	None	None	NA	NA	
7. Signage			I.		
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA	
8. Miscellaneous Items					
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Al Simkins with MDE was onsite for the monthly inspection.				
Other Comments/Observations?	None				

