

Health, Safety, Environmental, Product Stewardship and Sustainability 115 Tabor Road Morris Plains, NJ 07950 www.honeywell.com

October 25, 2019

Mr. Edward Hammerberg
Technical Specialist/RCE Supervisor
Waste Division and Utilization Program
Maryland Department of the Environment
1800 Washington Boulevard, Suite 645
Baltimore, MD 21230

Re: Transmittal of Quarterly Site Progress Report, Third Quarter 2019, 2000 Race Street Site, Baltimore, Maryland

Dear Mr. Hammerberg:

Please find attached the Third Quarter 2019 Site Progress Report for the 2000 Race Street Site, Baltimore, Maryland. This document is provided on behalf of Honeywell and the Mayor and City Council of Baltimore pursuant to the requirements of Section III.A of the 2000 Race Street Site Consent Order effective May 23, 2007.

If you have any questions or require additional information, please do not hesitate to contact me at 973-455-3302, or by e-mail at Maria. Kaouris@Honeywell.com.

Sincerely,

Maria Kaouris

Remediation Manager

Attachment

cc: Mr. Ed Dexter-MDE

Mr. Al Simpkins—MDE

Ms. Dawn Lettman—City of Baltimore Mr. Ravic Miller—City of Baltimore Mr. George Pfeiffer—Honeywell

Ms. Jessica Telano—Honeywell

THIRD QUARTER 2019 RACE STREET QUARTERLY SITE PROGRESS REPORT

2000 RACE STREET BALTIMORE, MARYLAND

Prepared for



115 Tabor Road Morris Plains, New Jersey 07950

and

Mayor and City Council of Baltimore, Maryland

Prepared by



Jacobs Engineering 2411 Dulles Corner Park Suite #500 Herndon, VA 20171

OCTOBER 2019



Contents

1.	Introduction	1
2.	Quarter in Review	1
3.	Upcoming Work and Submittals during the Fourth Quarter of 2019	2
4.	Schedule	2
Appe	endixes	
Α	Site Inspection Reports	



1. Introduction

Honeywell International Inc. (Honeywell) and the Mayor and City Council of Baltimore City (City) are submitting this Quarterly Site Progress Report for the 2000 Race Street Site (Site) pursuant to the May 23, 2007, Administrative Consent Order (Consent Order) between the Maryland Department of the Environment (MDE), Honeywell, and the City. Quarterly Site Progress Reports will be submitted to MDE for the duration of the Consent Order. As specified within Section III.F of the Consent Order, the reports are required to include the following information:

- Work completed, and documents submitted to MDE in the preceding guarter;
- A schedule and submittals for the upcoming quarter; and
- Any delays, modifications, or changes anticipated in the upcoming quarter.

This report covers Site-related activities conducted under the Consent Order during the third quarter of 2019, from July 1, 2019, through September 30, 2019.

The Site is located at 2000 Race Street, in Baltimore, Maryland (ZIP Code 21230). It occupies approximately 10.3 acres and is bounded on the north by the Baltimore Gas and Electric Spring Gardens facility, on the south by Swann Park, on the east by Race Street, and on the west by the Middle Branch of the Patapsco River. In addition, two elevated spans of Interstate 95 (I-95) oriented from east to west, overlie the Site on the northern half of the property. A chain-link security fence is present at the perimeter of the Site. The Site has no onsite building structures and is currently vacant.

Controlled hazardous substances are contained on the Site and covered with an engineered cap consisting of the following materials from top to bottom: asphalt, gravel base, and compacted clay. Cap maintenance is ongoing. Additional information regarding the Site is provided in several documents, including the May 23, 2007, Consent Order; the Site Characterization Work Plan, dated September 2007; the Site Characterization Report, dated September 2009; the Near Shore Investigation Report, dated December 2009; the Interim Remedial Measures Assessment Investigation and Pilot Test Report, dated July 2012; the Supplemental Site Characterization Report (former arsenic shed area), dated February 2018; Interim Remedial Measures Assessment (IRMA) Report, dated August 2018; Post-Closure C Controlled Hazardous Substance (CHS) Report, dated August 2018; and the Corrective Measures Alternatives Analysis Report, date August 2018.

2. Quarter in Review

Site-related activities performed during the third quarter of 2019 include the following:

- July 18: Monthly Site status inspection (Appendix A);
- July 26: Second Quarter 2019 Site Progress Report submitted to MDE;
- July 31: Project Coordinator call with MDE;
- August 1: Revised CHS Permit Application and CMAA submitted to MDE;
- August 14: Submitted enhanced cap engineering drawings and specifications to MDE;
- August 23: Monthly Site status inspection (Appendix A);
- August 28: Project Coordinator call with MDE;
- September 3: Performed site-wide vegetation control;
- September 11: MDE held public hearing on CHS permit;
- September 16-30: Installed new monitoring wells/inclinometers;
- September 20: Submitted Permeable Reactive Barrier (PRB) Operation and Maintenance Plan to MDE;



- September 23-30: Performed site preparation activities for new cap installation;
- September 26: Monthly Site status inspection (Appendix A); and
- September 27: CHS permit issued by MDE.

3. Upcoming Work and Submittals during the Fourth Quarter of 2019

The following activities and submittals are anticipated to occur in the upcoming quarter:

- Conduct monthly Site status inspections and participate in monthly Site status calls with MDE (October, November, and December);
- Submit the Third Quarter 2019 Site Progress report;
- Perform quarterly Semi-annual Shape Accel Array (SAA)/inclinometer readings; and
- Completed site preparation and install new enhanced containment cap starting in early October with demobilization in mid-November

4. Schedule

A schedule of Consent Order activities anticipated during the fourth quarter of 2019 is provided below.


Milestone	Anticipated Date
October 2019	
Mobilization to install enhanced containment cap	10-7-19
Perform monthly site status inspection	10-24-19
Submit Q3 2019 Site Progress report	10-30-19
November 2019	
Perform monthly site status inspection	TBD
Perform quarterly SAA/inclinometer readings	TBD
Complete cap installation and demobilization	TBD
December 2019	
Perform monthly Site Status inspection	TBD

2 GES1025190750WDC

Appendix A Site Inspection Reports


	,			
Inspector:	Bill Morris	Date of Inspection:	18-Jul-19	
Title:	Environmental Engineer	Date of Last Inspection:	20-Jun-19	
Organization:	CH2M HILL	Weather:		Hot, sunny
Site Inspection				
Task 1. General	Observations	Actions Taken	Date Completed	Comments/Additional Observations
Inspect site for presence of surface debris. Identify	9: Sediment and debris accumulation with	None	NA	Sediment, debris, and vegetation to be removed in
type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	vegetation growth	Notic		2019 as part of site maintenance before the installation of a new asphalt cap during Q4 2019.
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	2: Vegetation growth along shoreline	None	NA	Vegetation removal scheduled to be performed as part of site maintenance before the installation of a new asphalt cap during Q4 2019
2. Interstate 95 Footings and Joints				
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	Signs of asphalt settlement around pier footing	None	NA	Asphalt leveling to be performed as part of the new cap installation to be performed during Q4 2019.
	None	None	NA	NA
3. Engineered Cap	<u></u>	<u></u>		,
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	7: Alligator cracking in asphalt with vegetation growth	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	10: Groundhog borrow hole through asphalt	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
	Crack in asphalt with vegetation growth Crack between pier footing and asphalt with vegetation growth	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	4: Wide crack in asphalt with vegetation growth 11: Crack between pier footing and asphalt with vegetation growth	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for any signs of ponding of water	None	None	NA	NA
Inspect shorefront embankment for evidence of erosion or releases	None	None	NA	NA
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA
4. Fence	l	I.	ı	
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site	None	None	NA	NA

Site Inspection	Results			
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA
Inspect gates, chains, and locks for damage	None	None	NA	INA
Inspect fence to determine if any vegetation is damaging or otherwise compromising fence	3: Vegetation growth along fence	None	NA	Vegetation removal scheduled to be performed as part of site maintenance before the installation of a new asphalt cap during Q4 2019.
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA
5. Aboveground Stormwater Conveyance System		•	1	
Inspect aboveground stormwater conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	None	None	NA	NA
6. Vandalism		·		
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA
Identify any other observations related to vandalism on the site	None	None	NA	NA
7. Signage		•		
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)		None	NA	NA
8. Miscellaneous Items			L	
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Al Simkins of MDE on site for the montl	nly inspection.		
Other Comments/Observations?	8: Erosion at edge of stormwater let do	wn on slope. Cap repairs to be perfor	med as part of the insta	llation of the new cap during Q4 2019.



Inspector:	Bill Morris	Date of Inspection:	23-Aug-19	
Title:	Environmental Engineer	Date of Last Inspection:	18-Jul-19	
Organization:	CH2M HILL	Weather:	Hot, sunny	
Site Inspection			15.6	
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
1. General		I	1	
Inspect site for presence of surface debris. Identify type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	10: Sediment and debris accumulation with vegetation growth	None	NA	Sediment, debris, and vegetation to be removed in 2019 as part of site maintenance before the installation of a new asphalt cap during Q4 2019.
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	3: Vegetation growth along shoreline	None	NA	Vegetation removal scheduled to be performed as part of site maintenance before the installation of a new asphalt cap during Q4 2019
2. Interstate 95 Footings and Joints	•	•	•	
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	Signs of asphalt settlement around pier footing	None	NA	Asphalt leveling to be performed as part of the new cap installation to be performed during Q4 2019.
	None	None	NA	NA
3. Engineered Cap		•		
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	Alligator cracking in asphalt with vegetation growth	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	11: Groundhog borrow hole through asphalt	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for cracks less than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	6: Crack in asphalt with vegetation growth 7: Crack between pier footing and asphalt with vegetation growth	None	NA	Surface cover repairs to be addressed in 2019 as part of scheduled site maintenance and cap repairs.
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	5: Wide crack in asphalt with vegetation growth 1: Crack between pier footing and asphalt with vegetation growth	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for any signs of ponding of water	None	None	NA	NA
Inspect shorefront embankment for evidence of erosion or releases	None	None	NA	NA
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA
4. Fence		l		

_	•	te inspection oneckist		
Site Inspection				
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA
Inspect gates, chains, and locks for damage	None	None	NA	NA
Inspect fence to determine if any vegetation is damaging or otherwise compromising fence	4: Vegetation growth along fence	None	NA	Vegetation removal scheduled to be performed as part of site maintenance before the installation of a new asphalt cap during Q4 2019.
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA
5. Aboveground Stormwater Conveyance System		I .		
Inspect aboveground stormwater conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation		None	NA	NA
6. Vandalism		l e e e e e e e e e e e e e e e e e e e		
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA
Identify any other observations related to vandalism on the site	None	None	NA	NA
7. Signage	1		I	
	None	None	NA	NA
8. Miscellaneous Items	I	'		1
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Al Simkins of MDE on site for the monthly in	spection. Surveyors from RK&K on	site.	
Other Comments/Observations?	9: Erosion at edge of stormwater let down o	n slope. Cap repairs to be performe	d as part of the installa	tion of the new cap during Q4 2019.



	•	•		
Inspector:	Bill Morris	Date of Inspection:	26-Sep-19	
Title:	Environmental Engineer	Date of Last Inspection:	23-Aug-19	
Organization:	CH2M HILL	Weather:		Hot, sunny
Site Inspection	Results			
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
1. General				
Inspect site for presence of surface debris. Identify type, approximate volume of debris, and location via description or on Site Plan (attach to Monthly Site Inspection Checklist).	5: Sediment and debris accumulation with vegetation growth	City performed site-wide vegetation control	9/3/2019	Sediment, debris, and vegetation to be removed in 2019 as part of site maintenance before the installation of a new asphalt cap during Q4 2019.
Inspect site for presence of vegetation. Identify estimated amount and location of vegetation via description or on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
2. Interstate 95 Footings and Joints				
Inspect around pier footings for settlement. Identify settlement off-set from grade and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	Signs of asphalt settlement around pier footing	None	NA	Asphalt leveling to be performed as part of the new cap installation to be performed during Q4 2019.
	None	None	NA	NA
3. Engineered Cap				
Inspect cap for alligator cracking. Identify estimated area of cracking and location via description or on Site Plan (attach to Monthly Site Inspection Checklist)	6: Alligator cracking in asphalt.	None	NA	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for holes. Identify number of holes, width and depth, and location via description of on Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
Inspect cap for cracks less than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	3: Crack between pier footing and asphalt with vegetation growth	City performed site-wide vegetation control	3-Sep-19	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for cracks greater than 0.5 inches wide. Note number of cracks. Identify location of cracks via description or on Site Plan (attach to Monthly Site Inspection Checklist).	2: Wide crack in asphalt with vegetation growth	City performed site-wide vegetation control	3-Sep-19	Surface cover repairs to be addressed as part of new cap installation during Q4 2019.
Inspect cap for any signs of ponding of water	None	None	NA	NA
Inspect shorefront embankment for evidence of erosion or releases	None	None	NA	NA
Identify any other observations related to the condition of the cap and potential for cap damage	None	None	NA	NA

4. Fence

Site Inspection	Results			
Task	Observations	Actions Taken	Date Completed	Comments/Additional Observations
Inspect fence for holes. Note number of holes. Identify location of holes via description or on Site Plan (attach to Monthly Site Inspection Checklist).	None	None	NA	NA
Inspect fence to determine if there is any erosion compromising the integrity of the fence	None	None	NA	NA
Inspect fence to determine if barbed wire is in good condition	None	None	NA	NA
Inspect gates, chains, and locks for damage	None	None	NA	NA
Inspect fence to determine if any vegetation is damaging or otherwise compromising fence	None	None	NA	NA
Inspect fence to determine if there is any burrowing beneath fence	None	None	NA	NA
Identify any other observations related to the condition of the fence and potential for fence damage (e.g., points of weakness, corrosion)	None	None	NA	NA
5. Aboveground Stormwater Conveyance System	'n			
Inspect aboveground stormwater conveyance system including piping, downspouts, and drain in southwest corner of site for proper operation	None	None	NA	NA
6. Vandalism			•	
Inspect site for any vandalism including any dumped material on-site and damage to monitoring wells	None	None	NA	NA
Identify any other observations related to vandalism on the site	None	None	NA	NA
7. Signage				
Inspect warning signs on exterior perimeter of fence to determine condition and readability. Identify number of signs removed/damaged/unreadable and locations via description or Site Plan (attach to Monthly Site Inspection Checklist)	None	None	NA	NA
8. Miscellaneous Items				
Any interaction with people on or adjacent to the site? If yes, identify who, title, organization, contact information, and content of interaction	Sylvie Osias of MDE on site for the monthly	y inspection. Crews from Parratt Wo	lf and Flanigan on s	ite preparing for site construction.
Other Comments/Observations?	4: Erosion at edge of stormwater let down	on slope. Cap repairs to be performe	ed as part of the ins	tallation of the new cap during Q4 2019.

